SPARE PARTS Bulletin

P-EC-2205

Replacement Green Flashlight

PALFINGER EUROPE GMBH
Kapellenstraße 18, 5211 Lengau/Austria

June 29th, 2022
PALFINGER Crane / Service- and spare part manager

1 Description

PALFINGER wants to inform with this bulletin about the phase out of the flashlight **EEA5439**, **EEA5440**, **EEA5441**, **EEA5441U**, **EEA5658**, **EEA9797**, **EEA9798**, **EEA9846**, **EEA10021**, **YE81258A, YE81259.**

Due to a product improvement, the new flashlight **EEA15937** gets introduced to the market with the replacement kit **EEA5441AU**.

The parts of both versions (old and new) are fully interchangeable.

2 Old flashlight



- EEA5439 (3m cable), EEA9797 (8m cable)
- EEA5440 (5m cable), EEA9846 (5m cable)
- EEA5441 (8m cable), EEA10021 (3m cable)
- EEA5658 (1m cable), EEA9798 (1m cable)
- YE81258 (3m cable)

3 Replacement kit EEA5441AU

		
EEA15937	EEA17020	EEA5790

4 Electrical connection

In case of using the cable EEA5790, you have to connect the new flash light, equipped with a reverse polarityprotection, as follows:

Brown wire → Plus 12VDC or 24VVDC (+)

Blue wire → Minus 12VDC or 24VDC (-)

5 Release information

PALFINGER creates SPARE PART Bulletins in German and English. All other languages are translations.

Hamm Markus		Balthasar Gwechenberger			
Creator	June 29th, 2022	Released	June 29th, 2022	Translation	